flashLED - MPLAB IDE v8.36

File Edit View Project Debugger Programmer Tools Configure Window Help

Debug

Checksum: 0xbe00

flashLED.mcw

Output

Build | Version Control | Find in Files | PICkit 2

Initializing PICkit 2 version 0.0.3.63
Found PICkit 2 - Operating System Version 2.32.0
Target power not detected - Powering from PICkit 2 (5.00V)
PKWarn0003: Unexpected device ID: Please verify that a PIC12F629 is correctly installed in the application. (Expected ID = 0xF80, ID Read = 0x0)

PICkit 2 Warning

PKWarn0003: Unexpected device ID: Please verify that a PIC12F629 is
correctly installed in the application. (Expected ID = 0xF80, ID Read = 0x0)

☐ Don't display this warning again

OK

Help