

TWO TRANSISTOR FORWARD CONVERTER

VIN=+48V

K L1 L2 0.997

**Magnetising current =
 $I(L1) + 2.11 \cdot I(L2)$**

VOUT=-40V

