


SINGLE DIGIT SCOREBOARD - v3



NOTES:

To enable display connect a push-to-make switch to "DISPLAY ON" connections. If not using a switch then link these two connections.

To increase the counter, connect "-Trig" to 0v, "+Trig" to +V momentarily using a switch or similar.

To reset counter, switch off and back on again.

3 connections at top for PIR - pin compatible with Maplin sensor (YD85G).

If using the PIR then be sure to leave +Trig disconnected to prevent damage to PIR.

