

The 'Little t' device fails to meet the minimum system design specifications

- 1.) Incorrect Voltage Reference (IC3= 1% (0.1% Recommended))
- 2.) Incorrect Probing Resistors in Most Kits (R1-R6)

These errors are significant, and will impact the usefulness of this device. The software can not correct for these errors.

Note: This clone version does not have either of the circuit protection options, TVS or relay.

