



NOTES

THE METAL TAGS OF THE MOSFETS SHOULD NOT BE SHORTED TOGETHER, IF HEAT-SINKING IS REQUIRED PROPER INSULATION KITS WILL BE REQUIRED.

LINK OSC TO STEP FOR INTERNAL STEP GENERATOR, AJD. VR1 FOR SPEED CONTROL

LINK DIRECTION TO SELECT +5V OR GND VIA A SWITCH FOR DIRECTION CONTROL

