


91-849 REV 01



NOTES:

1. DEPTH BARE WIRE IS CUT OFF AT TRANSDUCER END.
2. CUT OF THE ORANGE WIRE AT BOTH ENDS.